

State of Ohio Environmental Protection Agency

**Southwest District Office** 

40 South Main Street Dayton, Ohio 45402-2086 (513) 285-6357 FAX (513) 285-6249

EPA Region 5 Records Ctr.

RE:

Bob Krazyce

George V. Voinovich Governor

August 7, 1991

SOUTH DAYTON DUMP MONTGOMERY COUNTY DRAFT SSI REPORT USEPA ID# OHD980611388

Ms. Jeanne Griffin Site Assessment Section Office of Superfund USEPA, Region 5 230 South Dearborn Street Chicago, Illinois 60604

Dear Ms. Griffin:

Ohio EPA has received and reviewed the FIT-prepared Draft Screening Site Inspection Report (dated July 9, 1991) for the South Dayton Dump site located in Dayton, Montgomery County, Ohio.

The agency has one comment concerning the report. Please provide the rationale for the deletion of the two sediment samples specified by the SSI workplan. According to the workplan, a total of thirteen samples, eleven soil and two sediment samples, were to be taken. The SSI workplan does indicate that the location of the samples were subject to change based on field conditions. However, the workplan does not indicate that the two sediment samples were to be taken conditionally, based on the findings of the site reconnaissance inspection.

Ohio EPA appreciates the opportunity to review and comment on this document and looks forward to seeing a revised copy of the SSI report which incorporates our concerns.

Please contact me at (513) 285-6058 if you have any questions or wish to discuss the above comment in more detail.

Sincerely,

Ali M. Moazed

Division of Emergency and Remedial Response

Kathy Davidson, DERR, CO cc:

Brad Stimple, E&E

al M. Morgel